

# Oil Field Environmental Incident Summary

**Incident:** 20131201140322 **Date/Time of Notice:** 12/01/2013 13:56

**Responsible Party:** Hess Tioga Gas Plant

**Well Operator:** HESS TIOGA GAS PLANT LLC

**Well Name:** Hess Tioga Gas Plant

**Field Name:**

**Well File #:** 0

**Date Incident:** 12/1/2013 **Time Incident:** 07:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 129

**Rng:** 107

**Sec:** 1

**Qtr:**

**Location Description:** Waste water from OWS (Oil Water Separator) spilled to ground

**Submitted By:** Chad Zubke

**Received By:**

**Contact Person:** Chad Zubke  
10340 68th St NW Tioga, ND. 58852  
Tioga, ND 58852

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2000 Feet

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units
Oil	0	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	1	barrels	0	barrels

**Followup** **Units**

**Description of Other Released Contaminant:**

Waste water to injection well

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

***Potential Environmental Impacts:***

***Action Taken or Planned:***

Hose connection was isolated with valve. Absorbants have been used to collect pooled water.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 12/1/2013    ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release was contained and recovered with absorbents on gas plant site location, according to the report. No followup is necessary.